

ALTERNATOR PLUGS

Image	Numbers	Description
	VP-100 CKK7023-1.2-21 021.100.163.800	Daewoo (bipolar)
	VP-101 CKK7025-3.5-21 021.100.164.800	VW
	VP-102 CKK7021Q-2.2-21 021.100.165.800	Chrysler
	VP-103 CKK7026B-3.5-21 021.100.166.800	Opel
	VP-104 CKK7033Z-3.5-21 021.100.167.800	BMW
	VP-105 CKK7032Y-1.8-21 021.100.168.800	Ford (tripolar)
	VP-106 CKK7036G-2.2-21 021.100.169.800	Toyota (tripolar)
	VP-107 CKK7021-6.5-21 021.100.170.800	Hitachi (bipolar)
	VP-108 CKK7044-2.2-21 021.100.171.800	Hitachi
	VP-109 CKK7046E-2.2-21 021.100.172.800	ND (4 polar)

Image	Numbers	Description
	VP-110 CKK5052-1.5-21 021.100.173.800	24V 5 pins
	VP-111 CKK7037F6321 021.100.174.800	Hitachi 3 pin round
	VP-112 C1860 021.100.175.800	Hitachi 4 pin round
	VP-113 CKK7042A-1.5-21B 021.100.176.800	Delco 4 pins New
	VP-114 CKK7021-2.5-21 021.100.177.800	Renault Old (bipolar)
	VP-115 CKK7021-0.6-21 021.100.178.800	Renault New
	VP-117 CKK7041-1.2-21 021.100.179.800	Honda Denso
	VP-118 CKK7023D-2-21 021.100.180.800	Chrysler
	VP-119 CKK7027-2.8-21 021.100.181.800	Mitsubishi Chrysler
	VP-120 CKK7051B-2521A 021.100.182.800	IST

Motoplatt has a stock of various connectors for the most common car alternators.

These connectors can easily replace the old and broken ones to get the alternator operating again.



VP-001

Plug set

021.100.990.800

Including:

VP-100	VP-101
VP-103	VP-104
VP-105	VP-106
VP-107	VP-108
VP-109	VP-110
VP-113	VP-114
VP-115	VP-117
VP-118	VP-119



Stichtse Kade 47c

1244NV 's-Graveland, The Netherlands



+ 31 (0)35 656 8503



info@motoplatt.nl

www.motoplatt.nl